## MERIAL SAFETY DATA S. EET DPM 1112-4

"Essentially Similar" to U. S. Department of Labor Form LSB-OOS-4

	a i sa i si bibbin da ka	Derle Strations and FA	ERGENCY TELEPHONE NO.	and the section of		
McGean Chemica	ıl Co., Ir	nc. 2	13/861 12			
DDRESS 9520 E. CeeBee Dri	ve Downe		213) 803-431	ł		
RADE NAME AND SYNONYMS	1 12			<del> </del>		
	E-BEE B-6	)		<u> </u>		
HEMICAL NAME AND SYNONYMS  aluminum	oxidation	and corrosion	remover			
HEMICAL FAMILY compound	MOLECULAR FORMULA blend					
SECTION II	HAZARDOUS (	OMPONENTS OF MIXTL	IRES			
COMPONENT %	THRESHOLD LIMIT VALUE	COMPONEN	т %	THRESHOL LIMIT VALUE		
	(UNITS)			(UNITS)		
Hydrofluoric acid; less than 1	3	ppm				
Phosphoric acid; less than 5						
Isopropanol alcohol; 10	7.6° 1.00	(-1-4-)				
	SECTION III	PHYSICAL DATA				
이 것이 그렇게 살아보자 살아나면 하면 하셨습니요 얼마를 받아 하셨다면 하셨다면 하셨다는데 하는데 얼마를 했다.		SPECIFIC GRAVITY (H <sub>2</sub> O=1		1.03		
APOR PRESSURE (mm Hg.)	190	PERCENT VOLATILE		78		
VAPOR DENSITY (AIR=1)		BY VOLUME (%)  EVAPORATION RATE	same as			
same a solubility in water	s water complet	=1)	same as	Water		
		_ <del></del>				
clear, visc	ous liqui	d with IPA odo	I and the second			
The state of the s	V FIRE AND I	EXPLOSION HAZARD DA	TA			
SECTION I	PLASH POINT none up to and including initial boiling point		LOWER non-flamm			
ELASH POINT NONE up to and inc initial boiling po	int	(PERCENT BY VOLUME)	1011 11011	UPPER nable		
PLASH POINT NONE UP to and inc initial boiling po	int	The state of the s	\			
PLASH POINT NONE UP to and inc initial boiling po	int /a n/a					
PLASH POINT NOTE UP to and inc initial boiling po PIRE-EXTINGUISHING MEDIA n	int /a					

## THRESHOLD LIMIT VALUE vapors non-toxic EFFECTS OF OVEREXPOSURE Severe irritant to skin and eyes EMERGENCY AND FIRST AID PROCEDURES For eye contact, flush thoroughly with water/immediately seek medical attention. For skin contact, wash thoroughly with soap and water.

		SECTION VI REACTIVITY DATA
	UNSTABLE	CONDITIONS TO AVOID
STABILITY	STABLE	
INCOMPATIBILITY (M	aterials to avoid)	austic materials
HAZARDOUS DECOM	POSITION PRODUCTS	
HAZARDOUS	MAY OCCUR	CONDITIONS TO AVOID
POLYMERIZATION	WILL NOT OCCUR	

## SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

treat with lime and flush away with water

WASTE DISPOSAL METHOD

treat with lime, dilute with water and release to sewer

RESPIRATORY PROTE	CTION (Specify type)  none require	1	Definition of the Constitution of the St				area esta anticología de	CONTRACTOR STATE	Carrier Call Control
	LOCAL EXHAUST		SPECIAL						s feetily.
VENTILATION	MECHANICAL (General)		OTHER						
PROTECTIVE GLOVE	acid resistant	EYE PRO	TECTION ggles	or i	ace	shie	ld		

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Avoid damage to containers. Store @ 32-90 F

OTHER PRECAUTIONS

Do not contain in galvanized container